



Quick Start Guide

1 Turn On




Press  to turn on the scale


2 Turn Off



Double Tap  to turn off the scale

3 Tare Weight



Press "" to tare / zero the weight

4 Complete Manual



For complete user manual,
please visit:
acaia.co/manual/lunar



2-Years Limited Warranty

Outside the United States: Please contact your original place of purchase or your local distributor. Products that are purchased in the US and shipped or taken out of the country have a two year warranty for parts only. If your product fails within two years date of purchase, simply email us at support@acaia.co Please have the following information prior to contacting Acaia:

- 1) Proof of date of purchase.
- 2) Model and serial number (located on bottom of the product) acaia will contact you to determine the problem, and see if it can be fixed quickly and easily.

The customer is responsible for paying the freight charges and any duties for replacement parts that Acaia may send. Customer is also responsible to provide any labor required to repair the product.

The high quality workmanship of Acaia products bearing the Acaia trademark is guaranteed by: Acaia Corporation, USA